TOP SERVET

COPIES RECFIVED

OS ADMIN

SEC BR

P&DS

CSD

IPD

PSD-ICB

TID

DIAXX 4

Office

Act

25X1

25X1

Cy No.

1505 CP 24 22 47Z

T O P S E C R E T 242237Z

PRIORITY 5523

IDEALIST

ATTENTION:

SUBJECT: EVALUATION OF MISSION C495C

1. CAMERA B 8 WAS USED IN MISSION C495C FLOWN ON 18 SEPTEMBER PD

1965. PROCESSING WAS ACCOMPLISHED IN THE FIELD.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: SMALL STATIC DISCHARGE TRACES ARE PRESENT ON NSA-LG
BOTH EDGES THROUGHOUT THE MATERIAL. THE INBOARD EDGE ALSO CONTAINS

CAMERA ROLLER INDUCED TRACES. A MANUFACTURER'S SPLICE IS PRESENT

IN FRAME 763. FRAMES 759 AND 760 ARE DEGRADED BY A DIAGONAL PLUS DENSITY STREAK WHICH WAS PROBABLY INDUCED BY THE SPLICE. NINE BREAKDOWN SPLICES ARE PRESENT IN THE MATERIAL BUT NONE OF THEM ARE

POSITIONED INSIDE A FORMAT.

C. 9L SIDE: PROCESSING STAINS APPEAR ON THE OUTBOARD EDGES

OF FRAMES 5, 256, 788, 888 AND 889. FRAMES 582, 584 AND 648

CONTAIN EMULSION BLISTERS. BOTH FILM EDGES DISPLAY INTERMITTENT

NON-LINEAR PLUS DENSITY STREAKS. FRAME 593 CONTAINS A MANUFACTURER'S SPLICE WITH ASSOCIATED ABRASIONS. NINE BETWEEN-FRAME BREAKDOWN

SPLICES ARE PRESENT IN THE MATERIAL.

D. BOTH SIDES: THE METERING IS SLIGHTLY IRREGULAR. THE TITLED FRAMES ARE NUMBERED 0005 TO 0889.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING

1	25X1
1	Excluded from sutomatic
-	Acceptable and
į	ANGRESS OF THE

THP SECRET

FAULT

- 3. DUPLICATE POSITIVE:
 - A. THE PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURED 10 PERCENT OF THE TERRAIN COVERED IN THIS MISSION.

TOPSECRET

/END OF MESSAGE/